



Transmission Services

Real Power Loss Return, V9 Response to Customer Comments

Posted: June 5, 2012

This document contains the Transmission Customer comments and Transmission Services' response to those comments for the Real Power Loss Return, Version 9, Business Practice posted for review from April 12, 2012 through May 10, 2012.

Thank you for your comments.

Table of Contents

1. Powerex	1
------------------	---

1. Powerex

Powerex has the following comment on the Real Power Loss Business Practice, Version 9:

In section C.8.f, the Business Practice has been modified so that "Northern Intertie owners" is now a required Product Suffix Code on the e-tag. Powerex asks that BPA explain the necessity for this distinction.

Transmission Service's Response

The Northern Intertie Owners loss return suffix code was added when it was discovered that it had been inadvertently omitted from previous versions of the Real Power Loss Return Business Practice. The listing of loss return suffixes listed in the Real Power Loss Return Business Practice now matches the listing of loss return suffixes found in the Scheduling Transmission Service, Version 8, Business Practice in Section B.4.